



Figure 41. Metal Spray Deposits on the Second-Stage Stator Vanes